US GM_SATURN, Judi Williams @ US_GM_DET_RN101, Kirk Jacobson @ US_GM_DET_RN101, William D. Balton @ US_GM_R.T_SPOO1, Vernon J. State @ SMAC, FCN Team @ US_GM_DET_RN101
US_GM_DET_RN101, Lori A. Cohylaki @ US_GM_DET_GMS, Terry Born @ US_GM_DET_RN101

WARRANTY INFORMATION METHORS SYSTEM WING DCS314 UNGSET DISTRIBUTE INMEDIATELY:

DATE:

MARCH 05, 1999

SUBJECT:

PRODUCT SAFETY CAMPAIGN 98065 BRAKE SHITCH WIRING POLARITY

MODELS:

1994 CHEVROLET AND GMC C/K

TO:

ALL CHEVROLET AND GMC

ATTN:

SERVICE, PARTS, AND WARRANTY MANAGERS

This campaign bulletin, minus your assigned VIN listing, is being forwarded to you at this time in order to take care of those customers who bring their vehicle in for inoperative brake lamps prior to their notification of this campaign.

can probably will not begin notifying owners of this campaign until late April, 1999. That is when parts are expected to be available in sufficient quantities to support this campaign. A VIN listing will be sent to dealers at that time.

In the meantime, should an owner bring in a 1994 C/K because the brake lamps exhibit the condition described in the "Defect Involved" section of this bulletin, check the VIN against VISS to determine whether the vehicle is included in the campaign bulletin.

- If it is included in VISS, repair the vehicle per this
 compaign bulletin, and charge the repair to the compaign
 using the campaign labor operation number.
- If the vehicle is not included in the campaign bulletin population, treat as a customer-pay repair.

CONDITION

General Motors has decided that a defect which relates to motor vehicle safety exists in all 1994 Chevrolat and GMC C/K model vehicles. These vehicles were built with polarity of the wiring for the sero adjust brake switch reversed from what was specified on the switch drawing. With the reversed polarity, the contacts in the brake switch can wear out prematurely. The brake switch will perform normally until the brake switch contacts wear out. When worn out, the contacts fail to close when the brake pedal is pressed. This results

in the loss of the brake lamps without any warning to the driver, which could fail to warn a following driver that the vehicle is braking and could lead to a vehicle accident.

To prevent the possibility of this condition occurring, dealers are to replace the brake switch and reverse the wiring.

VEHICLES INVOLVED

Involved are all 1994 Chevrolet and GMC C/K model vehicles built within the following VIN breakpoints:

IMPORTANT: Dealers should confirm vehicle eligibility through VISE (Vehicle Information Service System) prior to beginning campaign repairs.

REIMBURSENCENT :

Due to the nature of this campaign, customers may request reinhursement for prior brake switch replacement(s). Reinbursement amounts are to be claimed on the campaign claim line in not item. (Refer to the "Claim Information" section of the campaign bulletin.)

MAILING INFORMATION:

The mailing of the dealer bulletin will begin on March 5, 1999. Customers will be notified, in phases, of this campaign by General Motors starting in late april, 1999.

Computer listings containing the complete Vehicle Identification Number, customer name and address data will be supplied in late April, 1999 when owner notification begins.

VISS INFORMATION:

VISS information will be available on March 9, 1999 for Chevrolet and GMC.

O US_GM_DET_GMB, Terry Born O US_GM_DET_RN101

GM SERVICE OPERATIONS DCS326

Urgent - Distribute Immediately

990-025

DATE:

APRIL 12, 1999

SUBJECT:

98065 - PRODUCT SAFETY CAMPAIGN

BRAKE SWITCH WIRING POLARITY

DEALER VIN LISTINGS AND OWNER NOTIFICATION (Reference WINS DCS314 issued March 05,1999)

TO:

ALL CHEVROLET AND GMC DEALERS

ATTN:

SERVICE, PARTS, AND WARRANTY MANAGERS

In March 1999, you were notified of the above mentioned campaign and instructed to perform this campaign on involved vehicles that were brought into your dealership for loss of brake lamps. At that time we did not contact customers. This is your notification that we will now begin contacting customers.

Due to the number of vehicles involved, we will notify customers in phases. A dealer listing will be mailed for this phase of owner notification. As additional phases are released, you will receive a dealer listing of your involved vehicles.

MAILING INFORMATION

The mailing of dealer listings and owner letters for phase one will begin on April 12, 1999.

END OF MESSAGE

GM WARRANTY OPERATIONS

US GM_CHI_SCIO1, Sels Mickenen & US_GM_LOS_MBLD1, Rebert Dreet & US_GM_DET_RN101,
Brian Combe & US_GM_DET_RN101, Themas Healths & US_GM_SATURN, Jeff Williams &
US_GM_CET_RN101, Kirk Jacobson & US_GM_DET_RN101, William D. Balland &
US_GM_FLT_BP001, Vernon J. States & GMAC, PCN Team & US_GM_DET_RN101, Lori A. Oshviski
& US_GM_DET_GMS, Terry Born & US_GM_DET_RN101, Jan Color & US_GM_PON_POCO1, Reed
Mickelliam & US_GM_PON_POCO1, Keren Reeb & US_GM_PON_POCO1, Henk Leasth &
US_GM_DET_RN101, Jack Partales & US_GM_PON_POCO1

WARRANTY INFORMATION METWORK SYSTEM WISS DONALS URGENT - DISTRIBUTE INSEDIATELY: 990-025

DATE:

MAY 21, 1999

SUBJECT:

98065 - PRODUCT SAFETY CAMPAIGN BRAKE SWITCH WIRLING POLARITY

DEALER VIN LISTINGS AND ORDER MOTIFICATION (REFERENCE WINS DC6326 1851ED APRIL 12,1999)

TO:

ALL CHEVROLET AND GMC DEALERS

ATTN:

SERVICE AND PARTS HANDGERS AND MARRANTY ACMINISTRATOR

This is your notification that we are now ready to begin the second and final phase of owner notification for campaign 98063.

A dealer listing will be mailed for this phase of owner notification.

MAILING INFORMATION:

The mailing of dealer listings and owner latters for phase two will begin on May 21, 1999.

END OF MESSAGE

ON TAXBANTY OPERATIONS